



OFFICE OF DEFECTS INVESTIGATION (ODI)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **August 23, 2010 at 05:36 PM**

Search Type : **VEHICLE**

Make: **AIRSTREAM**

Model or Model No.: **CLASSIC**

Model Year: **2009**

Make: AIRSTREAM

Model: CLASSIC

Model Year: 2009

Manufacturer: AIRSTREAM, INC.

Mfr's Report Date: JUL 22, 2010

NHTSA CAMPAIGN ID Number: 10V344000

NHTSA Action Number: N/A

Component: SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected: 737

Summary:

AIRSTREAM IS RECALLING CERTAIN MODEL YEAR 2005-2009 CLASSIC TRAVEL TRAILERS MANUFACTURED FROM MARCH 2005 THROUGH APRIL 2009 AND EQUIPPED WITH HYDRAULIC BRAKE CONTROLLER BY ACTIVE TECHNOLOGIES. IT IS POSSIBLE THAT THE BRAKE CONTROLLER CAN FAIL UNEXPECTEDLY CAUSING THE BRAKES ON THE TRAILER TO LOCK UP OR TO FAIL COMPLETELY.

Consequence:

THE LOCKING OF THE BRAKES OR BRAKE FAILURE COULD RESULT IN A LOSS OF VEHICLE CONTROL THAT COULD RESULT IN A CRASH AND POSSIBLE SERIOUS INJURY.

Remedy:

DEALERS WILL INSPECT THE BRAKE CONTROLLER AND IF FOUND TO BE DEFECTIVE IT WILL BE REPLACED FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING AUGUST 2010. OWNERS MAY CONTACT AIRSTREAM AT 937-596-6111.

Notes:

OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).