Airstream Stainless Exterior







Range Exhaust Vent

Installed Cost: **\$325**

Outlet Cover
Installed Cost: \$200



Cable Cover

Installed Cost: **\$225**

Airstream Stainless Exterior





AIRSTREAM





Exterior Shower Compartment

Installed Cost: **\$550**

Exterior Waterfill w/Lock

Installed Cost: \$375

www.ColonialAirstream.com | 800-265-9019

Airstream Stainless Exterior







Segment Protectors
Installed Cost: \$2100